

County Surveyor's Record, Tillamook County, Oregon

CHAINS

4S R8W

$\frac{1}{4}$
 28 | 27

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

One-quarter common to Sections 27-28, W.M., Tillamook County, Oregon

ORIGINAL:

Set a basalt stone 18" x 16" x 12", 12 inches in ground for $\frac{1}{4}$ sec. cor. mkd. $\frac{1}{4}$ sec. on West face from which:

- A fir, 60" diam. bears S61°15'E., 74 links dist. mkd. $\frac{1}{4}$ SBT,
- An Alder, 4" diam. bears S2°15'W 19 $\frac{1}{4}$ lks. dist. mkd. $\frac{1}{4}$ SBT

FOUND:

18" x 16" x 12" stone 10 inches above the ground with mks. " $\frac{1}{4}$ " on West side,
 Original 60" snag, S61°15'E., 48.8 ft. with all mks. gone.
 The original Alder BT is gone.

RESTORED:

I set 1" pipe 30" above the ground along side of stone.
 I mark 2 new BTs as follows:

- 22" Fir, S77°30'W., 72 ft. mkd. $\frac{1}{4}$ S28BT
- 20" Fir, S38°E., 24 $\frac{1}{2}$ ft. mkd. $\frac{1}{4}$ S27BT

RESTORED BY:

Leonard Whitmore, Tillamook County Deputy Surveyor

DATED: 2-22-67