

County Surveyor's Record, Tillamook County, Oregon

CHAINS

13  
14  
15

6S R10W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

Standard Section Corner Common to Sections 14-15 only,  
Tillamook County, Oregon

ORIGINAL: Samuel G. Candle, August 12, 1880

Set stone, 12" x 12" x 10" in dry gulch; and built stone mound as per instructions.

FOUND:

12" x 12" x 10" stone with 3 notches on S. Side and located in a mound of rock in a dry gulch. This corner was set by Candle in 1880 with no witnesses. An erroneous standard corner for Sections 14-15 is located 205 feet North of this original stone corner established by Wygant in 1908 is in such excessive E-W alignment, I rule his corner as void. I found original line blazes and a S.I.R.  $\frac{1}{2}$  mile post East of Candle's stone.

Wilson in 1890 used Candle's corner in subdivision of the Township to the North. I, therefore, accept Candle's 1880 stone as the true corner.

RESTORED:

I set a 1" pipe alongside the stone.

I mark 2 new BTs:

39" Spruce, N.10°E., 37 $\frac{1}{2}$  ft. mkd. T6SR10WS14CSBT.

18" Alder, N.37°W., 46 ft. mkd. T6SR10WS15CSBT.

RESTORED BY:

Leonard Whitmore, Tillamook County Deputy Surveyor

WITNESSED BY:

Ed Gary

DATED: 2-21-67

# County Surveyor's Record, Tillamook County, Oregon

CHAINS	
--------	--

CORNER RECORD (SEARCH)		Tract or Survey No. _____ No. <u>14 17</u>
File No. _____	R.D. <u>HeBO</u>	County <u>TILLA-LINCOLN</u>
T <u>6S</u> R. <u>10W</u>	N.F. <u>SIUSLAW</u>	State <u>ORE</u>
Merid. <u>WILL.</u>		
<p><b>CORNER DIAGRAM</b></p> <p>STD. SEC. COR. TO SECS 14-15 ONLY</p>	<p><b>DESCRIBE CORNER MONUMENT FOUND</b>                  FOUND 12 X 12 X 10 STONE WITH 3 NOTCHES ON S. SIDE AND LOCATED IN A MOUND OF ROCK IN A DRY GULCH. THIS CORNER WAS SET BY CAUDLE IN 1880 WITH NO WITNESSES.</p> <p><b>DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND</b>                  AN ERRONEOUS STANDARD CORNER FOR SECS. 14-15 IS LOCATED 205 FT. NORTH OF THIS ORIG. STONE CORNER ESTABLISHED BY WYGANT 1908 IS IN SUCH EXCESSIVE E-W ALIGNMENT I RULE THIS CORNER AS VOID. I FOUND ORIG. LINE BLAZES AND A S. 1/4 MI. POST EAST OF CAUDLES STONE.</p> <p><b>DESCRIBE CORNER LOCATION RELATIVE TO NEAR BY FEATURES, ALSO HOW TO REACH CORNER</b>                  WILSON IN 1890 USED CAUDLES CORNER IN SUBDIVISION OF THE TOWNSHIP TO THE NORTH. I THEREFORE ACCEPT CAUDLES 1880 STONE AS THE TRUE CORNER.</p>	
<p><b>PHOTO IDENTIFICATION DATA</b></p> Photo No. _____ Filed At. _____ Object Ident. _____ Ident. By _____ Signature _____		
<p><b>PLANE COORDINATE POSITION DATA</b></p> State _____ Zone _____ X _____ Y <u>BOOK 3</u> Estab. By _____ Agency _____		
Signature _____	Title _____	Division _____
_____	_____	Headquarters <u>HeBO</u>
_____	_____	Date _____
_____	_____	5680-2

CORNER RECORD (PERPETUATION)	
<p><b>MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT</b></p> <p>I SET A 1" PIPE ALONGSIDE THE STONE.</p>	9
<p><b>ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE</b></p> <p>I MARK 2 NEW BT'S:                  39" SPRUCE, N. 10° E., 37 1/2 FT. MKD. T6SR10WS14CS BT.                  18" ALDER, N. 37° W., 46 FT. MKD. T6SR10WS15CS BT.</p> <p style="text-align: right;">Leonard Whitmore, Tilla Co. Dep. Surveyor                  Ed Gory, witness</p>	10
Work Done By _____ Title _____ Date _____ State Registration No. _____ or Agency _____	11
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____	11
REMARKS	

BOOK 3							
Index File No.	T.	R.	M.	Tract or Surv. No.	Cor.		
BOOK 3							