

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 7, 8, 17 and 18, T3N,
R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (1873) (now missing), from which a:

12" Hemlock bears S35W 11 lks.; missing.
9" Hemlock bears N40W 6 lks.; missing.
9" Hemlock bears S44°E 10 lks.; missing.
12" Hemlock bears N40°E 12 lks.; missing.

NOTE: The GLO surveyor returned to this corner in 1893 and found
the post rotted and BT's down.

RESTORATION by GLO surveyor in 1893

Post (now missing, found 26" Hemlock stump, at corner point with
scribes S18 on SW face, S7 on NW face, some visible on badly
rotted SE face, and T3N R on NE face) from which a:

12" Hemlock bears N49°E 39 lks.; now 24" uproot, scribes BT visible
on partially exposed face.
7" Hemlock bears S11°E 42 lks.; rotten wood in place.
7" Hemlock bears N48W 15 lks.; now 24" stub 2' high, top missing.
7" Hemlock bears S29W 44.5 lks.; now badly rotten stub, scribe W
visible on upper face, B visible on lower face.
Found $\frac{1}{2}$ " iron pipe S40W 3.2 ft. from corner stump.

REWITNESSED

Var. $21\frac{1}{2}$ °E

From above corner stump:

52" Hemlock bears N23 $\frac{1}{2}$ W 66.0 ft.; scribed T3N R10W S7 BT RS 707.
14" Hemlock bears N34 $\frac{1}{2}$ °E 46.0 ft.; scribed T3N R10W S8 BT.
19" Hemlock stump bears S24W 32.1 ft.; scribed T3N R10W S18 BT.
27" Hemlock stump bears S79°E 47.5 ft.; scribed T3N R10W S17 BT.


Oregon State Forestry Department metal location poster on South side
of corner stump.

Dated March 31, 1969.

Rewitnessed by



Harold J. Russell



Present and witnessed by Stanley Gann.