

Index

File No.

T 4 S R. 9 W

S. HeBo


County TILLA.

Merid. Will.

N.F. SIUSLAW

State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND GLD 1879 SET ALDER POST + MKD.

- A 18" MAPLE, N. 83° W., 87 LKS.
- A 46" SNAG, S. 73° W., 5 LKS.
- A 30" SNAG, S. 79° E., 29 LKS.
- A 48" SNAG, N. 56° E., 25 LKS.

TILLA. CO. SURVEYOR 1895 SET  
4x8x22 STONE MKD. + ON TOP  
AND "CS" ON N. SIDE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

M. WHITMORE, USFS, 1-21-63. BY RECORD FOUND A  
22x8x4 STONE, MKD. CS ON N. SIDE & + ON TOP AND  
RE WITNESSED 2 ALDERS:

- 25" ALDER, S. 15° W., 9 FT. BARK SCRIBED T5SR9WS5BT.
- 27" ALDER, N. 45° W., 28 FT. BARK SCRIBED T4SR9WS32BT.

PHOTO IDENTIFICATION DATA

Photo No. EIJ-9-140

Filed At

Object Ident.

Ident. By

*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

I FOUND THE STONE AND ALDERS AS DESCRIBED BY  
WHITMORE. THE ORIG. N.W. MAPLE HAS VISIBLE "BT"  
MARKS IN OPEN FACE. THE ORIG. SW, SE, AND NE  
MARKS ARE BADLY BURNED AND DECAYED WITH ALL  
MARKS GONE. I PUT BT SIGNS ON WITNESSES.  
SET ALUMINUM GUARD POST 2 FT. NE OF CAR.

*Signature*  
Leonard Whitmore

*Title*  
Forestry Tech

*Division*  
Timber

*Headquarters*  
Hebo

*Date*  
4-18-69 7100-52 (3/68)