


1. T. 5 S. R. 9 W. No. 12-11 Cor. Mer. Will State. ^(rectangular) ORE N. F. SIOUPLAW Dist. HEBC

2. Corner Status Original Description Vol. Page Where Recd



4. Description of Corners:
TILLA COUNTY SURVEYOR 1887 SET A POST AND MARKED 2 BT:
28" SNAG, S. 60° W., 43 LKS.
30" SNAG, N. 31° E., 163 LKS.

7. Photo Identification
Photo No. EIJ-7-265
Ident. By:

5. Investigation Notes:
THE CORNER POINT SETS ON EDGE OF A LOGGING SKID ROAD.
POST IS MISSING.
I FOUND A 40" SAWED OFF SNAG, N. 31° E., 163 LKS. WITH FAINT
SCRIBE MARKS "1/4 SBT"

8. Plane Coordinate Position Data
State Zone
X
Y
Estab. By
Field Book No.
Where Filed

FOUND 28" ROTTED SNAG, S. 57° W., (NOT S. 60° W) 43 LKS. WITH
MARKS ROTTED OFF.

V-1

OVER

9. Evaluation
Authentic
Needs Verif. Monument
Re-estab. Survey
Land Status

6. Signed Leonard Whitmore Title Forestry tech Date 2-14-69

FRONT