


CERTIFIED RECORD OF LAND CORNER MONUMENT

History of original corner establishment:

Corner was set by William Anderson,  
Tillamook County Surveyor in February of 1951.



Description of corner evidence found:

Found a 6" x 6" x 20" wooden post mkd 1/16S on the east side  
from which

- A 12" pine snag brs S4W 7.0 ft; scribing exposed; tag good
- A 14" fir brs S66W 7.4 ft; face partially healed; tag good
- A 16" fir brs N74W 14.5 ft. face chopped out & partially  
rehealed; tag good

Description of monument and accessories established to perpetuate the  
original location of this corner

- Set a 2" x 30" iron pipe with brass cap mkd T 3 S R 10 W  
CW  
1/16 S18  
1969  
650
- Reset old post along side
- Set a 6" steel post west of corner with F.S. boundary sign  
facing north. Painted red band around each BT.



*Tom O. McCullough*  
JULY 10, 1964  
TOM O. McCULLOUGH  
650

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the ..... day of.....; 19....., at..... o'clock .....m., (signed)  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)