

Index
File No.

CORNER RECORD (SEE CH) (REF. FSH 7131.4)

Tract or
Survey No.

T 4S R. 10W

to H800


Country TILLA

Merid. Will.

N.F. SIOUXLAW

State ORE

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND
 GLO 1879 SET POST & MARKS;
 72" FIR, N. 35° E., 23 LKS.
 36" FIR, S. 20° W., 43 LKS

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 M. WHITMORE, USFS, 5-26-51 FOUND 72" SNAG, N. 35° E.,
 23 LKS. WITH FAINT SCRIBE MKS. "1/4".
 A 36" SNAG, S. 20° W., 43 LKS. WITH MARKS ROTTED OFF.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

WHITMORE SET A PIPE 1 FT. ABOVE GROUND &
 MARKED;
 24" FIR, S. 33° W., 13 ⁵/₈ FT. SLOPE DIST. MKD. 1/4 S 21 BT.
 16" FIR, N. 12° E., 37 FT. SLOPE DIST. MKD. 1/4 S 16 BT.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estob. By _____
Agency

Signature Leonard Whitmore Title Forest Tech Division Timber Headquarters N660 Date 3-25-76 7101-52 (3/53)