

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner established in 1878 by Henry Meldrum

In 1879 GLO set post and marked

72" fir brs. N35E 23 lks

36" fir brs. S20W 43 lks



Description of corner evidence found:

Found $\frac{1}{2}$ " pipe set by M. Whitmore in 1951 from which

36" fir snag brs. S20W 28.4 ft (orig)
no marks

72" snag brs. N35E 15.2 ft (orig)
faint scribe marks " $\frac{1}{4}$ "

28" fir brs. S33W 13.5 ft
scribed - with tag

20" fir brs. N12E 34.9 ft
scribed - with tag

Description of monument and accessories established to perpetuate the original location of this corner

Set 2"x30" iron pipe with brass cap mkd

T4S R10W

$\frac{1}{4}$ $\frac{16}{21}$
1970
650

Set pipe alongside corner

Set fence post with signs \pm 5 ft east facing south

Office of COUNTY SURVEYOR County of TILLAMOOK

State of OREGON, I hereby certify that the within instrument was filed in this office for record on the 1st day of July, 1970, at o'clock m., (signed)

[Signature]
(COUNTY OFFICIAL)

by (DEPUTY)

REGISTERED
OREGON
LAND SURVEYOR

[Signature]
JULY 10, 1964
TOM O. McCULLOUGH
650

4/1/70