


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1878 by Henry Meldrum



Description of corner evidence found:

Found 1/2" galvanized pipe set by M. Whitmore in 1949 from which

48" cedar windthrown brs. N40W 41.6 ft  
has face with old rusted location poster (orig)

32" fir brs. S88 1/2 W 46.0 ft  
scribed - with tag

50" hemlock brs. S71E 53.5 ft  
scribed - with tag

BTs mkd by M. Whitmore  
in July of 1962

Description of monument and accessories established to perpetuate the original location of this corner

Set 2"x30" iron pipe with brass cap mkd

T4S R10W

1/4 3 | 2

1970  
650

Placed 1/2" pipe alongside corner

Set fence post with Do Not Destroy sign.

Office of County Surveyor County of Tillamook  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 15<sup>th</sup> day of May, 1970, at        o'clock        m., (signed)

*[Signature]*  
(COUNTY OFFICIAL)

by        (DEPUTY)

REGISTERED  
OREGON  
LAND SURVEYOR

*[Signature]*  
JULY 10, 1964  
TOM O. McCULLOUGH  
650

BOOK 2 1

364

58.	T. 4S.	R. 10W.	⑤		
	Section 2	1/4 cor. Sect. 2, sec. 2 and 3.			
	Set a stake 2 in diam.	30 ins. high with 1/2" iron			
	pipe 14 ins. high	along side of stake from which			
	a 4" dead cedar snag 35 ft. high	bears,			
	N. 40° W. 63 lbs. with old blazed face on SE. side.				
		all berries and are rotted off. (old BT)			
		The SE. BT is gone.			
	a 29" lin S. 88° 30' W. 71 lbs. marked 4 S 3 BT. (New BT)				
	a 50" hemlock S. 71° E. 82 lbs. marked 4 S 2 BT. (New BT)				
	By M. Whitmore	June 21, 1962.			
	Lur				

Mervin Whitmore's private notes for a non-legal survey (he not being licensed) However he was a very reliable and competent man in his field work & surveying. J. Kentle es.