


CERTIFIED RECORD OF LAND CORNER MONUMENTS

History of original corner establishment:

Corner originally set by Henry Meldrum in 1879. He set post and scribed 2 BTs.  
M. Whitmore found corner in 1963. He set post and scribed 2 new BTs.



Description of corner evidence found:

Found a 4"x4" post with S33 on west face and S34 on east face from which

- A 36" snag brs. S30E 44.2 feet scribing and axe mark visible (orig)
- A 50" snag brs. S40W 2.6 feet mark rotted off (orig)
- A 16" fir brs. S53E 69.7 feet face healed (M. Whitmore, 1963)
- A 24" fir brs. N45W 56.1 feet face healed (M. Whitmore, 1963)

Description of monument and accessories I established to perpetuate the original location of this corner

Set a 2"x30" iron pipe with brass cap marked

T4S R9W

33 34

1970  
920

- Set Whitmore post beside corner
- Set steel fence post north of corner + 3 feet with F.S. attention sign facing west.
- Replaced BT tags and painted red on all BTs.

Office of COUNTY SURVEYOR County of TILLAMOOK  
 State of OREGON, I hereby certify that the within instrument was filed in this office  
 for record on the 9<sup>th</sup> day of SEPTEMBER, 1970, at ..... o'clock .....m., (signed)  
*[Signature]* by .....  
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED  
 OREGON  
 LAND SURVEYOR  
*[Signature]*  
 JULY 17, 1970  
 RICHARD L. BRYANT  
 920