

CHAINS

* 903

(Washington County records)

12 July 1893: $\frac{1}{4}$ Corner Common to Sec 18, T3N, R5W & Sec 13, T3N, R6W, W.M. A Hemlock post $3 \times 3 \times 3'$ set 18" in ground & marked $\frac{1}{4} S$ on W. Side, from which:
 Hemlock 10" dia N $42^{\circ} 30' W$ 10 Ks. marked S $\frac{1}{4}$ BT
 Hemlock 8" dia. S $74^{\circ} 30' E$ 20 Ks. marked S $\frac{1}{4}$ BT
 Both trees & post in good state of preservation.
 $\sqrt{22^{\circ} 30' E}$

Copied from A.A. Morrill, D.C.S., Field Book # 1, page 30.

* 904 May 1909, W.H. Barber, Co. Surveyor

July 1893: Section Corner Common to 7 & 18, T3N, R5W & 12 & 13, T3N, R6W, W.M. A Hemlock post $4 \times 4 \times 4'$, 2" in ground, marked

R6W S12	S7
T3N S13	R5W S18

 2 notches on N

& 4 notches on S. edge, from which:

Hemlock 24" dia. N $80^{\circ} 30' E$ 63 Ks. marked T3N R5W S7 BT
 Hemlock 12" dia. S $23^{\circ} 15' E$ 63 Ks. marked T3N R5W S18 BT
 Hemlock 36" dia. S $8^{\circ} 15' W$ 60 Ks. marked T3N R6W S13 BT
 Hemlock 10" dia. N $2^{\circ} 45' W$ 63 Ks. marked T3N R6W S12 BT
 BOOK 5 $\sqrt{22^{\circ} 30' E}$ BT'S & Post in good Condition.

Copied from A.A. Morrill, DCS, Field Book # 1, Pages 30 & 31.