

CHAINS

319

#900 Cont.

Fir 3 1/2" dia. N 44° 45' W 96 lks
 $\sqrt{22^{\circ} 30' E}$

Copied from A.A. MARRILL, D.C.S., Field Book #1, pages 27 & 28
 21 May 1969, H & L Barber, Co. Surveyor

#901

July 1893: 1/4 Sec. Corner Common to 19, T3N, R5W &
 24, T3N, R6W. A Hemlock post 3x3 ins. Sq marked
 1/4 S on E. & W. Faces from which;
 Fir 50" dia. bears S 57° 15' E 15 lks. I marked it 1/4 S BT
 Hemlock 24" dia. bears S 20° 15' W 12 lks. marked 1/4 S BT
 $\sqrt{22^{\circ} 30' E}$

Copied from A.A. Merrill, D.C.S., Field Book #1, page 28.
 21 May 1969, H & L Barber, Co. Surveyor (Win Co.)
 records

#902

July 1893: Section Corner, Common to 18 & 19, T3N, R5W &
 13 & 24, T3N, R6W. Govt. BT'S are;
 Hemlock 10" dia. N 44° 15' E 20 lks, down & marks not visible.
 Hemlock 8" dia. S 44° 15' W 22 lks marked S 24 on N.W. Face.
 Hemlock 8" dia S 74° 45' W 13 lks.

No other BT'S to be found.

(See next pg
 for complete
 report.)

Set a 4" x 4" x 4" Hemlock post 2' in ground, marked