


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by William P. Wright in 1882.



Description of corner evidence found:

Found 1½" x 36" iron pipe for corner to Sections 16,17 20, 21 with 1½" x24" iron pipe alongside from which

- A 16" hemlock brs. N2¼W 48.4 ft.
- A 22" hemlock snag brs. N33½E 11.2 feet
- A 27" spruce brs. S80¼E 25.9 feet
- A 47" fir brs. S253/4W 66.9 feet

* See same corner reported in Book 3 p 254 PR 70

Description of monument and accessories I established to perpetuate the original location of this corner

No monument established

Set 2 steel fence posts south and west of corner with Forest Service boundary signs.

Office of County Surveyor County of Tillamook
 State of OREGON, I hereby certify that the within instrument was filed in this office
 for record on the 23rd day of SEPTEMBER, 1970, at _____ o'clock _____ m., (signed)
[Signature]
 COUNTY SURVEYOR (COUNTY OFFICIAL) by _____ (DEPUTY)

REGISTERED
 OREGON
 LAND SURVEYOR

[Signature]
 JULY 10, 1964
 TOM O. McCULLOUGH
 650

BOOK 5

Form R6-7100-57 (9/66)

6/19/70