


CERTIFIED RECORD OF LAND CORNER MONUMENTA

History of original corner establishment:

Sam Caudle set a 10"x8"x5" stone in 1880.
Tillamook County Surveyor scribed a 54" snag
in 1887 and set a post. Snag brs. S61E 60 lks.
M. Whitmore found snag in 1955, set pipe and
scribed 2 new BTs.



See Book 1
Page 241
JLC

See Book 1
Page 2
JLC

Description of corner evidence found:

- Found 3/4"x30" iron pipe (Whitmore, 1955) from which
 - A 54" snag brs. S61E 39.6 ft
scribing barely visible (Tillamook Co. Surveyor, 1887)
 - A 20" alder brs. N25E 4 1/2 ft (Whitmore, 1955)
scribed 1/4 S24 BT
 - A 28" fir brs. NSW 53.7 ft (Whitmore, 1955)
face healed

Description of monument and accessories I established to perpetuate the original location of this corner

Set 2"x30" iron pipe with brass cap mkd

T5S R9W
1/4 30 | 39
1970
650

Reset 3/4" pipe beside brass cap.

Drove steel fence post ± 5 ft west of corner with F.S.
boundary and attention signs facing south
Painted red band & placed BT tags on BTs.

Office of COUNTY SURVEYOR County of TILLAMOOK
 State of OREGON, I hereby certify that the within instrument was filed in this office
 for record on the 10 day of JULY, 1970, at o'clock m., (signed)
John Caudle COUNTY SURVEYOR
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED
 OREGON
 LAND SURVEYOR
Tom O. McCullough
 JULY 10, 1964
 TOM O. McCULLOUGH
 650

6/1/70