CORNER REMONUMENTATION & RESTORATION TILLAMOOK COUNTY, OREGON

FOR

U.S. FOREST SERVICE SIUSLAW NATIONAL FOREST CORVALLIS, OREGON

APRIL, 1970


BY

McCullough, Bryant & Associates Corvallis, Oregon

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Closing corner was established in October of 1880 by Sam Caudle. He closed upon John Meldrum's line that he ran from east in 1872 to establish the standard corner to T6S, R9&10W.



Description of corner evidence found:

* Found 3/4" iron pipe in mound of stone as per records

A 17" alder brs. S32W 16.4 feet (not orig) bark scribing visible

Standard corner between Section 36, T5S, R10W and Section 31, T5S, R9W lies due west 33 feet.

* See attached supplement filed with this report by McCoccough 9/23/10 gk

Description of monument and accessories I established to perpetuate the original location of this corner

Set 2"x30" iron pipe with brass cap mkd

from which

An 18" alder brs. S89E 39.1 feet bark scribed T6S R9W S6 BT 650

Set a fence post with F.S. boundary sign and attention sign ± 3 ft south facing west Set a fence pst with F.S. boundary sign ± 2 ft west facing south.

Office of COUNTY SURVEYOR County of TLUL AMOOU State of OREGON, I hereby certify that the within Instrument was filed in this office COUNTY SURDEYOU SAL

REGISTERED OREGON LAND SURVEYOR

TOM O. McCULLOUGH

650

BOOK 5

Form R6-7100-57 (9/66)

Page 33- non elistent