

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 13 and 24, T3S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (found rotten remains 12" below ground surface) from which a:

14" Fir bears N.84°E. 8 lks.; now 24" stump, scribes/4 visible on partially exposed and burnt face (bearing N75°E).

12" Hem. bears S.50°W. 30 lks.; now 26" stump, scribing visible on partially exposed face.

RESTORED

VAR. 21-1/2° E.

Set 1-1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S13 S24 1969 RS707", 30 inches in ground, and from which a:

24" Fir stump (original BT) bears N75°E. 5.2 ft.; scribed 1/4 S13 BT RS707.

50" Fir stump bears S.26°E. 40.5 ft.; scribed 1/4 S24 BT.

Set 4" x 4" x 50" white painted Cedar post 1.0 ft NW of corner pipe. Oregon State Forestry Department metal location poster on 24" BT.

Dated May 19, 1970

Restored by

Present and witnessed by Keith Whitehead
Leonard Whitemore

