

County Surveyor's Record, Tillamook County, Oregon

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

CHAINS
Section corner common to Sections 7, 12, 13 and 18, Twp. 2 N., Rge. 9 and 10 W.,
Tillamook County, Oregon

ORIGINAL

Post (missing) from which a:

10" Fir bears S.64°E. 9 lks.; now a stub, bottom of face and
one piece of scribe visible.

8" Hemlock bears N.20°W. 23 lks.; uproot, face on bottom
side, cruiser mark visible.

6" Hemlock bears S.14°W. 29 lks.; uproot.

6" Hemlock bears N.10°E. 13 lks.; missing.

RESTORED

Var. 21-1/2 E.

Set 1-1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY T2N R9W R10W S7 S12 S13 S18 1970 RS 401",
33 inches in ground, and from which a:

31" Fir bears S.62°W. 44.1 ft.; scribed T2N R10W S13 BT RS401.

28" Fir bears S.22-1/2°E. 63.9 ft.; scribed T2N R9W S18 BT.

29" Hemlock bears N.35-1/2°W. 44.3 ft.; scribed T2N R10W S12 BT.

Set 4" x 4" x 50" white painted Cedar post 1.0 ft. SW of corner pipe.
Oregon State Forestry Department metal location poster on 29" Hem. BT.

Dated May 14, 1970

Restored by Charles E. Curl under my direction.
Charles E. Curl, Transitman

Present and witnessed by B. Henderson

S. Gann

