

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 16, 17, 20 and 21, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, found $\frac{1}{2}$ " iron rod 0.8 ft. SE of corner point) from which a:

- 8" Hem bears N80E 5 lks.; now 13" stub with scribe BT remaining on rotted face.
- 12" Hem bears S10E 31 lks.; now 21" rotted stump with scribe BT on lower face, upper fact cut off when logged.
- 6" Hem bears N52W 20 lks.; missing.
- 7" Hem bears S45W 22 lks.; now 12" badly rotted stub face and scribes rotted away.

RESTORED

Var 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W S16 S17 S20 S21 1969 RS707", 33 inches in ground, and from which a:


- 11" Hem bears S8 $\frac{1}{2}$ W 23.4 ft.; scribed T3N R9W S20 BT RS707.
- 12" Hem bears S88 $\frac{1}{4}$ E 17.9 ft.; scribed T3N R9W S21 BT.
- 9" Hem bears N13 $\frac{1}{4}$ W 14.0 ft.; scribed T3N R9W S17 BT.
- 11" Spruce bears N37E 7.9 ft.; scribed T3N R9W S16 BT.

Set 4" x 4" x 50" white painted Cedar post 1.0 ft. N.E. of corner pipe. Oregon State Forestry Department metal location poster on 11" spruce BT.

Dated May 29, 1970

Restored by Charles E. Curl, Transitman under my direction.

Present and witnessed by Jerry Grace



Harold Russell

