

CHAIN RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 7 and 18, T2N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

8" Hemlock bears S.44°E. 24 lks.; now a 24" stub, scribes 1/4S and part of the B exposed.

6" Spruce bears N.23°W. 9 lks.; missing

RESTORED

Var. 21-1/2°E.

Set 1-1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S7 S18 1970 RS 401", 33 inches in ground, from which a:

26" Hemlock bears N.76-3/4°E. 23.1 ft.; scribed 1/4 S7 BT RS401.


28" Hemlock bears S.61°E. 18.8 ft.; scribed 1/4 S18 BT.

Set 4" x 4" x 50" white painted cedar post 1.0 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 26" Hem. BT.

Dated May 14, 1970

Restored by Charles E. Curl under my direction.
Charles E. Curl, Transitman

Present and witnessed by B. Henderson
A. Tocchine



Richard A. Morris
MAY 10 1970
Richard A. Morris
Richard 401 Morris