

County Surveyor's Record, Tillamook County, Oregon

CHAINS

32 53 4510
5 4 5910

Found A 40" Fir with Sapling
in it saying "Axxv1"
This Tree Being A Bearing
Tree For Angle Point 26
From 1 Mile Point on Hudson
Counsh. Road with is Tied To
Sec. Cor. ^{32 53} 614.
Bearing Tree For Angle 26 WAS
12" Fir N53 $\frac{1}{2}$ W 19 $\frac{1}{4}$ Feet.
I Set This Point.
From Angle 26 To Sec. Cor. is
S65 W 88 $\frac{1}{4}$ Feet
So I set Cor From These Cols.
I Set A 2" Iron Pipe 36"
Long Flush with the Ground
Also Setting A 4"x4"x48" white
Cedar Post 0 $\frac{1}{2}$ East of Cor.
Corner Fall 13' Northly of East
West Fence Line.
Old 1872 Bearing Trees Are:
5" Willow N40W 69 $\frac{30}{100}$
5" Spr. N20 E 44 $\frac{22}{100}$
4" Spr. S50 W 19 $\frac{20}{100}$
14" Spr. S55 E 75 $\frac{30}{100}$

BOOK 5

These Bearing Trees are Now
Gone
Found one Bearing Tree
But Have No Record of
This Tree which is:
40" Fir N53 $\frac{1}{2}$ E 82 $\frac{10}{100}$ @ 17 $\frac{00}{100}$
Scribed "S23 T4510W"
Year Scribed 1915
New Bearing Trees Are:
24" Fir N40 $\frac{1}{2}$ E 59 $\frac{57}{100}$ @ 15 $\frac{00}{100}$
Scribed "T45R10W 533 BTCS"
16" Spr. S69 E 25 $\frac{02}{100}$
Scribed "T55R10W 548 BTCS"
14" Spr. N63 W 51 $\frac{12}{100}$
Scribed "T45R10W 532 BTCS"
14" Hem (Turn with 105 per on Rotten stub)
S 29 $\frac{1}{2}$ W 70 $\frac{25}{100}$ @ -17 $\frac{00}{100}$
Scribed "T55R10W 55 BTCS"

H. Duncan
Stan Skinner 4-6-67

BOOK 5

10/25/71 J. H. Collier C.S.

BOOK 5

