

County Surveyor's Record, Tillamook County, Oregon

18" Hemlock stub, rotted, N 40° W 6.2 feet; scribe visible.

CHAINS

11" Hemlock N 80° E 7.1 feet; found old face grown over.

8" Spruce snag S 56° E 7.2 feet; scribe visible.

28" Hemlock S 47° W 15.3 feet; found apparent grown over face, and old cruiser's initials.

I referenced 26" Spruce South 7.57 feet; screw nail, lead washer, yellow tag.

thence N 87° 11' W between sections 3 and 10.

1206.8 Set a 1½" x 36" stainless steel pipe in the ground for the property corner established by proportionate measurement by Longview Fibre Company.

$\frac{S \ 3}{S \ 10} \ E \ 1/16$

2413.6 The 1/4 corner. Found spruce limb for corner and original bearing tree as recorded by Longview Fibre Company in 1967.

$\frac{S \ 3}{S \ 10} \ 1/4$

Beginning at the E 1/16 corner common to sections 3 and 10 heretofore described

thence N 2° 07' E along the N-S centerline of the SE¼ section 3.

768.0 Main ridge, bearing N 70° E

1305.3 Set a 1½" x 36" stainless steel pipe for the SE 1/16 corner established by intersecting the N-S centerline and E-W centerline of the SE¼ by Longview Fibre Company.

S 3

SE 1/16

From which:

30" Hemlock bears N 45° W 26.8 feet; scribed "SE 1/16 S3 BT"; screw nail, lead washer, yellow tag.

36" Hemlock bears S 74° E 24.17 ft.; scribed "SE 1/16 S3 BT"; screw nail, lead washer, yellow tag.

2163.0 Draw, course N 58° E.

2610.6 The C-E 1/16 corner. Found 1½" stainless steel pipe as established by Longview Fibre Company in 1967 and previously recorded.

S 3

C-E 1/16

BOOK 5