


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: NONE




Description of corner evidence found: NONE

SEE MAP B-985
 FOR REVISED CORNER
 POSITION 7-17-81
 Allan & Duncan C.S.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2"x30" galvanized iron pipe, flared at the bottom and a brass cap riveted on top, extending 2" above ground.

Set steel post with Forest Service signs 2.0ft west of monument



New Bearing trees as follows:

- 10" Cedar scribed " 5 1/16 52 BT " N59°05'E 16.45ft.
- 12" Cedar scribed " 5 1/16 53 BT " S2°07'E 26.92ft.

Placed USFS bearing tree signs on each tree breast high facing monument.

Office of CLATSOP COUNTY SURVEYOR County of TILLAMOOK
 State of OREGON, I hereby certify that the within instrument was filed in this office
 for record on the 16 day of JUNE, 1971, at 9 o'clock A.m., (signed)
[Signature] by [Signature]
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED
 OREGON
 LAND SURVEYOR

[Signature]
 JULY 12, 1963
 AUGUST C. GIERING
 608

BOOK 5

CLARK & GROFF ENGINEERS, INC.
 3276 COMMERCIAL STREET S. E.
 SALEM, OREGON