


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: *NOVE*




Description of corner evidence found: *NOVE*

*SEE MAP B-985
FOR REVISED CORNER
POSITION 7-17-81
Allan Duncan C.S.*

Description of monument and accessories established to perpetuate the original location of this corner

Set 2" x 30" galvanized iron pipe flared at the bottom and a brass cap riveted on top, extending 3" above the ground.

Stamped Disk



Set steel post with Forest Service Sign 50ft west.

New Bearing Trees as follows:

18" Fir scribed " C 1/4 53 BT" S31°W 23.37ft.

7" Spruce scribed " C 1/4 53 BT" N88°15'E 6.32ft.

Placed USFS Bearing tree signs on each tree breast high facing monument.

Office of COUNTY SURVEYOR County of TILLAMOOK
 State of OREGON, I hereby certify that the within instrument was filed in this office
 for record on the 10 day of JUNE, 1971, at 9 o'clock A.m., (signed)
[Signature] (COUNTY OFFICIAL) by _____ (DEPUTY)

CLARK & GROFF ENGINEERS, INC.
 3276 COMMERCIAL STREET S.E.
 SALEM, OREGON

REGISTERED
 OREGON
 LAND SURVEYOR

[Signature]
 JULY 12, 1967
 AUGUST C. GIERING
 608

BOOK 5

Form R6-7100-57 (9/66)