


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1899. Records in Book 3 Page 246 state: Set berry stake for $\frac{1}{16}$ cor from which a Hemlock 36" bears $S 39^{\circ} E 58.1$ fs. a Spruce 36" bears $N 16^{\circ} E 71.1$ fs.



Description of corner evidence found:

Found 2" x 60" iron pipe extending 30" above the ground as found by Anderson in 1937. Also old bearing trees established in 1899 as follows.

A well rotted hemlock stump $S 39^{\circ} E$ 38.3ft. measuring to center of stump.


A well rotted spruce stump $N 16^{\circ} E$ 47.0ft measuring to center of stump.

Description of monument and accessories established to perpetuate the original location of this corner

At position of 2" iron pipe. Set 2" x 30" galvanized iron pipe flared at the bottom and a brass cap riveted on top extending 3" above the ground with the 2" iron pipe along side.

Set steel post with Forest Service signs 5.3 ft East of monument

Stamped Disk.



New bearing trees as follows:

12" Hemlock $S 78^{\circ} W$ 25.78ft scribed "SW $\frac{1}{16}$ S4 BT"

8" Spruce $S 38^{\circ} 15' E$ 15.80ft scribed "SW $\frac{1}{16}$ S4 BT"

Placed U.S.F.S. Bearing tree signs on each tree at breast height facing monument.

Office of County Surveyor County of TILLAMOOK
 State of OREGON, I hereby certify that the within instrument was filed in this office for record on the 16 day of JUNE, 1971, at 9 o'clock A.m., (signed)
[Signature] by [Signature]
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED
 OREGON
 LAND SURVEYOR

[Signature]
 JULY 12, 1963
 AUGUST C. GIERING
 608

CLARK & GROFF ENGINEERS, INC.
 3276 COMMERCIAL STREET S. E.
 SALEM, OREGON

BOOK 5

Form R6-7100-57 (9/66)

BOOK 5

168