


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: *NONE*



Description of corner evidence found: *NONE*

*SEE MAP B-985 FOR
REVISED CORNER POSITION
7-17-81 Allen & Duncan C.S.*

Description of monument and accessories established to perpetuate the original location of this corner

Set 2" x 30" galvanized iron pipe, flared at the bottom and brass cap riveted on top, extending 6" above the ground.

Stamped Disk →

T55 R10 W
SE 1/4 S3
1971
608

Set steel posts with Forest Service signs 4.0 ft. South, 5.0 ft West, 5.0 ft East and 5.0 ft North.

New Bearing trees as follows:

*6" Fir scribed " SE 1/4 S3 BT" 586°30'W 18.13 ft.
21" Fir scribed " SE 1/4 S3 BT" N65°05'E 14.45 ft.*

Placed U.S.F.S. bearing tree signs on each tree breast high & facing monument.

Office of County Surveyor County of Tillamook
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 10 day of JUNE, 1971, at 9 o'clock A.m., (signed)
[Signature] C.S. by *[Signature]* (DEPUTY)
(COUNTY OFFICIAL)

REGISTERED
OREGON
LAND SURVEYOR

[Signature]
JULY 12, 1963
AUGUST C. GIERING
608

BOOK 5

CLARK & GROFF ENGINEERS, INC.
3276 COMMERCIAL STREET S. E.
SALEM, OREGON

Form R6-7100-57 (9/66)