


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally established by the G.L.O. They set a post at 80.00 chains North of the corner common to T.5 and 6S R.10 and R11W.

80.00 Set post for corner 25 and 36

- An Elder 4" diam. N.50°W. 57 links
- Elder 3" diam. N.10°E. 31 links
- Elder 3" diam. S.20°E. 39 links
- A Spruce 16" S.10°W. 70 links



(Contract Survey)

Description of corner evidence found:


I found a 1" capped pipe <sup>BENT</sup> by a windfall at the corner. The "elders" are gone, but the Spruce is still alive and has been opened up to where the scribing is visible. There were also 2 other stumps marked as BT's.

*70 li or 40 li?*

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 2"x30" Iron pipe with a flared bottom and a brasscap riveted to the top marked:

*70 li or 40 li?*



I tied to the existing BT's and retagged them. I also scribed and tagged a new BT to the S.E.

- 74" Spruce S.10°W. 46<sup>2</sup> ft. (scribing partially visible)
- 90" Spruce stump N.71°W. 95<sup>0</sup> Ft. (scribing visible)
- 31" Spruce stump N.32°E. 36<sup>9</sup> Ft. (scribing visible)
- 3/4" Iron pipe N.35<sup>1</sup>/<sub>2</sub>°W. 64<sup>8</sup>ft. (no record)

I marked: 59" Spruce S.58°E. 70<sup>2</sup> ft., mkd. "T5S R10W S31BT"

I set 6 foot steel posts 5 feet South and 5 feet East of the corner with "Attention" and "Property Boundary" signs on them.

Office of COUNTY SURVEYOR County of TILLAMOOK  
 State of OREGON, I hereby certify that the within instrument was filed in this office  
 for record on the 12<sup>th</sup> day of October, 1971, at 9:30 o'clock A.m., (signed)  
*John L. Conlin* COUNTY SURVEYOR (DEPUTY)  
 (COUNTY OFFICIAL)

Witnessed:

M. Yinger

Set this 21st day of September 1971

REGISTERED  
 OREGON  
 LAND SURVEYOR

*Kenneth M. Wightman*

JULY 17, 1970  
 KENNETH M. WIGHTMAN II  
 942