

County Surveyor's Record, Tillamook County, Oregon

CHAINS

(147)

SW 1/4 Sec 29 359

Found A 1/2" Iron Pipe 6" Above The Ground
 No Bearing Trees, I know this pipe
 is in this place because of old
 Transit work done By JLCorlich &
 Myself through out the years
 I set 1 1/2" Iron pipe in place
 of The 1/2" Iron pipe.

New Bearing Trees
 I set A 4x4x48 white Ced post on N 55 E
 Side of Pipe + 2' Past Cor.
 Has A Al. Strip Marked "SW 1/4 29 359"
 45 03 10" Fir N19°45 E @ 19°33' 48 42 "SW 1/4 S29 BTCS
 33 49 6" Fir S89° E @ 20°25' 35 12 " " "
 8" Alder N23° E 12' Tag Set By JLC 287
 9-19-53

SASKinner 12-7-66
 A. Durcan
 G. Arthur
 See A-264
 " A-351

BOOK 5

OK J. L. Corlich C.S.
 11/12/71