

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner had never been established.

DIAGRAM M
Section 6
C-W-W-NW
1/256

Reference:
Plat dated July 1973 by
Timberland Services, Inc.
under my stamp.

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

I established the location of this corner by proportional measurement. The location of this corner falls on the running surface of U.S. Highway 101.

I, therefore, set a "PK nail" at the corner, from which a:
2 1/2" X 30" galvanized iron pipe N 0° 18' 39" E 26.83 ft.
brasscap marked:

T 6 S R 10 W
S 6
C-W-W-NW
1/256 RM
1973 ↓
RLS 942

RR spike S 0° 18' 39" W 48.87 ft.

No BT's available

Witnessed: M. Jackson

Office of County Surveyor County of Tillamook
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 25th day of August 1973 at 9:12 o'clock A. M., (signed)
J. M. Wightman by
(COUNTY OFFICIAL) (DEPUTY)

Set this 25th day of July 1973.

BOOK 5 Edgar L Cook

241

Graduate Forest Engineer
Form R6-7100-57 (9/66)

TIMBERLAND SERVICES, INC.
P.O. Box 668 - Albany, Ore. 97321
Phone: 928-3539

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Kenneth M. Wightman
OREGON
JULY 17, 1970
KENNETH M. WIGHTMAN II
942