

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner had never been established.

DIAGRAM 0  
Section 6  
NW-SW-NW  
1/256

Reference:

Plat dated July 1973 by  
Timberland Services, Inc.  
under my stamp.

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T 6 S R 10 W  
S 6  
NW-SW-NW  
1/256  
1973  
RLS 942

by proportional measurement.

From which a :

- 36" Hemlock N 16° E 8.8 ft.  
mkd "NWSWNW 1/256 S 6 BT"
- 46" Hemlock N 34° W 13.8 ft.  
mkd "NWSWNW 1/256 S 6 BT"

Witnessed: M. Cook

Office of County Surveyor County of Tillamook  
State of Oregon I hereby certify that the within instrument was filed in this office  
for record on the 20<sup>th</sup> day of August, 1973, at 8:57 o'clock A.m., (signed)  
[Signature] by [Signature]  
(COUNTY OFFICIAL) (DEPUTY)

Set this 30th day of July 1973.

BOOK 5

Edgar R Cook

243

Graduate Forest Engineer  
Form R6-7100-57 (9/66)

TIMBERLAND SERVICES, INC.  
P.O. Box 668 - Albany, Ore. 97321  
Phone: 928-3539

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Kenneth M. Wightman

OREGON  
JULY 17, 1970  
KENNETH M. WIGHTMAN II  
942