

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 5 and 8, Township 3 North, Range 10 West, W.M., Tillamook County, Oregon.

ORIGINAL

8" x 4' tall Hemlock stub found in 1966 (now missing) from which a:

20" Hemlock bears N66°W 24 lks.; now missing, in windfall area.

7" Hemlock bears S73°W 18.5 lks.; see restoration below.

RESTORATION by State of Oregon, Department of Forestry (1966)

1 1/2" x 36" galvanized iron pipe with 3" bronze cap (now torn out by windfall in area) from which a:

12" Hemlock bears S20°E 18.3 ft. to face; now 12" stump, scribes 1/4 S8 BT visible on open face.

21" Hemlock bears N37°E 10.2 ft. to face; now 21" stump, scribes 1/4 S5 BT RS707 visible on open face.

26" Hemlock (original) bears S73°W 12.2 ft.; now 26" x 5' high windfall stub, scribes BT visible on open face.

Yellow Metal Location Poster on 17" Hemlock N17°W 3.2 ft; now 17" windfall.

RESTORED

Var. 21 1/2°E

Reset 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S5 S8 1966 RS707", 34 inches in ground, in mound of rock, and from which a:

7" Hemlock bears N35°W 91.5 ft. to face; scribed 1/4 S5 BT RS707.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NW of corner pipe. Oregon State Forestry Department metal location poster on 21" Hemlock stump N37°E 10.2 ft.

Dated April 8, 1974

Restored by Charles W. Cook under my direction.
Charles W. Cook, Forest Engineer

Present and witnessed by K. Whitehead
B. Henderson
P. Hufstader

BOOK 5

BOOK 5

