

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OR. GOV. DEPARTMENT OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14,
T6S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 12" Fir bears S50°E 39 lks.; now missing.
- 15" Fir bears S78°W 29 lks.; now missing.
- 12" Fir bears N49°W 28 lks.; new 20" uprooted stump, scribes R9W visible.
- 12" Fir bears N23°E 21 lks.; now missing.

RESTORED

-Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "O. GOV. DEPT. OF FORESTRY T6S R9W S11 S12 S13 S14 1961 RE2311", 32 inches in ground, and from which a:

- 43" Fir bears S28°W 30.4 ft.; scribed T6S R9W S14 BT RE2311.
- 17" Hemlock bears N63°W 41.9 ft.; scribed T6S R9W S11 BT.
- 27" Fir bears N9°E 32.9 ft.; scribed T6S R9W S12 BT.
- 5" Alder bears S65°E 12.4 ft.; scribed T6S R9W S13 BT (in back).

Oregon State Forestry Department metal location poster on 27" BT.
Center Line of State Highway 18 bears West 32.0 ft.
Set 4 x 4 x 72" white painted Cedar post 2.0 ft. SE of corner pipe.

Dated March 5, 1962

Restored by Billy E. Davis under my supervision.
Billy E. Davis, Transactor

Present and witnessed by R. Schulson

