

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

North One-Sixteenth corner common to Sections 2 and 3, T1S, R9W, W.M.,
Tillamook County, Oregon.

ORIGINAL

2-1/4" x 28" galvanized iron pipe with 3" bronze cap marked N1/16
S3 S2 1959 by U.S. Cadastral Engineers (found lying near by, torn out
by uproot) from which a:

32" Hemlock bears S56°E 36 lks.; now 37" stump, scribes N1/16S
2 BT visible on partially closed face.
21" Hemlock bears N56°W 56 lks.; now missing.

RESTORED

Reset above 2-1/4" x 28" pipe 26 inches in ground, in mound of rock, and
from which a: Var. $21\frac{1}{2}^{\circ}$ E

37" Hemlock stump (orig.) bears S56°E 23.8 ft. to face; scribed
RS707.
6" Hemlock bears N55°W 18.7 ft. to face; scribed N1/16 S3 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SW of corner (pipe).

Dated October 8, 1974

Restored by Keith D. Whitehead under my direction.
Keith D. Whitehead, Compass Man

Present and witnessed by Richard L. Nyseth
James Soeth

