


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally set by the G.L.O. in 1880 under Contract No. 364. They set a stone 12"x6"x4" and built a stone mound.




Description of corner evidence found:

I could find no evidence of the original corner.

Description of monument and accessories I established to perpetuate the original location of this corner

At proportionate distance, I set a 2 1/2" x 30" galvanized iron pipe with a brasscap riveted to the top marked:



from which:

- 5" Hemlock N 59° E 39.5 feet  
mkd. "X" & 3 nails in base
- 3" Hemlock S 45° W 29.6 feet  
3 nails in base

All bearing trees have been banded with red paint and attention signs and BT tags have been attached. All scribes have a 3/4" brass washer, with "LS 942 engraved on it, nailed in the face.

Witnessed: E. W. Tatro

Office of ..... County of .....  
 State of ..... , I hereby certify that the within instrument was filed in this office  
 for record on the ..... day of .....

..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

Set this 11th day of February 1975

*Monte A. Cook*  
 Monte A. Cook  
 Forest Technician

322

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Kenneth M. Wightman*

OREGON  
JULY 17, 1970  
KENNETH M. WIGHTMAN II  
942



**TIMBERLAND SERVICES, INC.**  
 1010 Airport Road P. O. Box 668  
 Albany, Oregon 97321  
 Telephone (503) 926-9404

LAND SURVEYING - ENGINEERING  
 LAND USE PLANNING - ROADS  
 FORESTRY CONSULTING