

County Surveyor's Record, Tillamook County, Oregon
County Surveyor's Record, Tillamook County, Oregon

CHAINS
CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

CU
Southeast ~~corner~~ one-sixteenth corner for Section 12, T3N, R10W, W.M.,
Tillamook County, Oregon.

ORIGINAL

Oregon State Board of Forestry pipe and cap (found in place) from which a:

50" Hemlock bears S31°E 112.7 ft.; now 56" in place, face grown over.
36" Spruce bears N24°W 96.6 ft.; now 42" in place, face grown over.

REWITNESSED

Var. 21½°E

Original pipe and cap, from which a:

24" Spruce bears N86°W 54.7 ft. to face; scribed SE 1/16 S12 BT RS 707.

Set 4" x 4" x 50" white painted Cedar post 1.0 ft. SW of corner pipe.
Oregon State Forestry Department metal location poster on 24" Spruce BT
N86°W 54.7 ft. Also poster on 50" Hemlock BT S31°E 112.7 ft.

Dated December 16, 1974.

Rewitnessed by *C. Wayne Cook* under my direction.
C. Wayne Cook, Engineer

Present and witnessed by Keith D. Whitehead

