

County Surveyor's Record, Tillamook County, Oregon  
County Surveyor's Record, Tillamook County, Oregon

CHAINS  
CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

East one quarter corner for Section 1, T2N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 6" x 13" x 9" (missing) from which a:

18" Hemlock bears N72°E 15 lks.; now 24" with scribes visible on partially exposed face (now bears N58°E).

24" Hemlock bears N11°W 48 lks.; now a 30" stump with scribes 1/4 S visible.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S1 1974 RS 707," 34 inches in ground, in mound of rock, and from which a:

6" Hemlock bears N79¼°W 39.6 ft. to face; scribed X BT RS 707.

9" Hemlock bears S46½°W 16.6 ft. to face; scribed 1/4 S1 Bt.

Spring branch bears North 103', course N88°E from same.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NW of corner pipe. Oregon State Forestry Department metal location poster on 7" Fir S67½°E 7.1 feet.

Dated December 16, 1974.

Restored by

*Loren R. Steele*  
Loren Steele, Forest Engineer

under my direction.

Present and witnessed by Terry Withrow

