

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 10 and 15, T3N, R6W, W.M.,
Tillamook County, Oregon.

ORIGINAL

Stake (missing, see note below) from which a:

50" Fir bears N11½°E 14 lks.; destroyed by road construction.
40" Cedar bears S50°E 20 lks.; destroyed by road construction.

RESTORATION by L. W. Amort, November 17, 1955.

1½" x 36" galvanized iron pipe with 3" bronze cap, (see note below) from which a:

6" Fir bears S30°E 10.4 ft.; destroyed by road construction.
6" Fir bears N12°W 3.0 ft.; destroyed by road construction.

Note: The corner and accessories were within a road construction
right of way. The corner was referenced on September 17, 1973,
and reset later from said reference points.

RESTORED

Var. 21½°E

Reset 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY 1/4 S10 S15 1955 RE 2311," 42 inches in ground,
in ditch line on South edge of road, and from which a:

15" Fir bears S1½°E 29.1 ft. to face; scribed 1/4 S15 BT RS 707.
18" Fir bears N39°E 42.5 ft. to face; scribed 1/4 S10 BT.
C.L. of camp 5 road bears East 19; course N40°W by S 40°E.

Set 4" x 4" x 60" white painted Cedar post 24.1 ft. South of corner pipe.
Oregon State Forestry Department metal location poster on 15" Fir BT.

Dated March 31, 1975

Restored by Steve Ellis under my direction.
Steve Ellis, Compassman

Present and witnessed by Terry Withrow

