

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 19, 20, 29 and 30, T1N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

No evidence of original corner found.

REESTABLISHMENT by Russell Bass, May 7, 1965.

17" Fir corner tree (missing, torn out by road construction) from which a:

5" Cedar bears N36°E 9.6 ft.;	] destroyed by road construction
27" Fir bears N61°W 29.0 ft.;	
13" Hemlock bears S77°W 10.3 ft.;	
17" Fir bears S48°E 11.9 ft.;	

Note: The corner and accessories were within a road construction right of way. The corner was referenced on May 23, 1973, prior to construction, and reset later from said reference points.

RESTORED

Var 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R9W S19 S20 S29 S30 1974 RS707", 46 inches in ground, 12" below surface of road, in center of spur road, N87°W by N83°E, and from which a:

25" Fir bears N32°W 65.0 ft. to face; scribed T1N R9W S19 BT.  
 22" Fir bears N68 ¾°E 156.0 ft. to face; scribed T1N R9W S20 BT RS707.  
 19" Fir bears S63°W 61.1 ft. to face; scribed T1N R9W S30 BT.  
 29" Hemlock stump bears S63½°E 71.2 ft. to face; scribed T1N R9W S29 BT.

Set 4" x 4" x 60" white painted Cedar post 14.2 ft. South of corner pipe. Oregon State Forestry Department metal location poster on 25" Fir BT. Also poster on above 4" x 4" x 60" Cedar post.

Dated April 4, 1975.

Restored by Keith Whitehead under my direction.  
Keith Whitehead, Compassman

Present and witnessed by Mike Nordin

