

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 26 and 27, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

No evidence of original corner found.

REESTABLISHMENT by Richard A. Morris, December 31, 1959.

1½" x 36" galvanized iron pipe with 3" Bronze Cap, found in place, from which a:

18" Hemlock bears S75½°E 27.3 ft.; now 26" stump, face grown over.
19" Hemlock bears N793/4°W 13.5 ft.; now 26" burnt, uprooted stump.

REWITNESSED

Var 21½°E

From above monument, in good condition a:

44" Hemlock bears S51°W 57.4 ft. to face; scribed ¼ S27 BT RS707.
64" Spruce Stump bears N33 3/4°E 47.0 ft. to face; scribed ¼ S26 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on spruce stump BT. Also poster on 8" spruce S43°W 30.1 feet.

Dated April 4, 1975.

Restored by C. Wayne Cook under my direction.
C. Wayne Cook, Forest Engineer

Present and witnessed by K. Whitehead
M. Nordin

