

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 1 and 12, T3S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

4" Hemlock bears N90°E 18 lks.; now 8" windfall, face partially closed, scribes rotted away.

26" Hemlock bears S51°E 14 lks.; now 28" stump in place, scribes 4S visible on partially closed face.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R8W ¼ S1 S12 1975 RS707", 34 inches in ground, and from which a: Var. 211½° E

25" Hemlock bears S15½°E 32.2 ft. to face; scribed ¼ S12 BT.

20" Hemlock bears N23¼°W 40.8 ft. to face; scribed ¼ S1 BT RS707.

Road centerline bears West 102.6 ft. S48°W by N18°W.

Found 1" iron pipe NW 1.5 ft.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 6" Hemlock N14°W 12.6 ft.

Dated April 2, 1975.

Restored by C. Wayne Cook under my direction.
C. Wayne Cook, Forest Engineer

Present and witnessed by Keith D. Whitehead
Michael E. Nordin

