


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

1887 GLO set post
15" Fir bears N 77° 45' E 190 lks
22" Fir bears S 16° 30' E 103 lks
12" Fir bears N 45° W 100 lks




Description of corner evidence found:

1" galvanized pipe with 4" x 4" white post 1 ft. N
36" Fir stump bears N 77° 45' E 125.4 ft. with scribe marks "T6S R8W S6 BT" showing
The SE Bearing Tree is stump
The NW Bearing Tree is missing
16" Fir bears N 21° E 23 ft. to side center
22" Fir bears S 20° E 14 ft. to side center

Corner is located 112 ft. North of logging road

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2" galvanized pipe with 3" Brass Cap 6" above ground stamped:
Placed 1" galvanized pipe in hole on North side of monument
Set steel post with Attention sign 2 ft. South of monument
Painted 6" red band and faces of blazes on witnesses
Placed Attention signs on backs of bearing trees



See map B. 701



Office of County Surveyor County of Tillamook
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 17th day of NOVEMBER, 1975
Frank L. Hall, C.S. by _____
(COUNTY OFFICIAL) (DEPUTY)