

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 13 and 24 (East end), T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 36" Spruce bears N48°W 65 lks.; missing, in skid road fill slope.
- 75" Fir bears S46°W 48 lks.; now 78" stump, no marks remaining.
- 6" Maple bears S62°E 54 lks.; missing, saplings in place.

RESTORATION by L.W. Amort, 1952.

OSBF 1½" x 36" pipe and cap (found pulled out and leaning against Fir BT) from which a:

- 18" Fir bears N25°W 49 lks.; now 31" face grown over.
- 9" Spruce bears S39°W 126 lks.; now 12" face grown over.
- 18" Hemlock with yellow metal location poster bears N36°W 18 ft.; now 28" N30°W 12.5 ft., which agrees with marks on poster.

RESTORED

Var. 21½°E

Set the above 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N, R9W, S13 S24 1952 2311", 34 inches in ground, in center of skid road, course S75°W by N30°E, in mound of rock, and from which a:

18" Fir (Amorts B.T.) bears N25°W 31.7 ft. to face; scribed RS707.

Set 4" x 4" x 5' white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on 34" Fir N79°E 32.7 ft.;

Dated November 10, 1975

Restored by C. Wayne Cook under my direction.  
C. Wayne Cook, Forest Engineer

Present and witnessed by Keith D. Whitehead

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Harold J. Russell*  
OREGON  
JULY 9, 1965  
HAROLD J. RUSSELL  
707

BOOK 5