

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

## RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 27, 28, 33 and 34, T3N, R6W, Tillamook and Washington Counties, Oregon.

ORIGINAL

Post (missing) from which a:

- 48" Fir bears N73°45'E 22 lks.; now a rotten 41" stump with no marks visible.
- 10" Hemlock bears S61°15'E 12½ lks.; now root holes in place.
- 10" Hemlock bears S73°W 42½ lks.; missing.
- 10" Hemlock bears N42°W 40 lks.; missing.
- 10 lk. creek bears South 5.50 chains, course N60°W; in place.
- Spring branch bears North 5.25 chains, course West; in place.
- 8 lk. creek bears West 4.75 chains, course NW; in place.
- 2 lk. creek bears East 6.25 chains, course S15°W; now 340', course S55°W.
- 48" Hemlock line tree bears North 10 lks.; now badly rotted stub in place.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W S27 S28 S33 S34 1975 RS707", 34 inches in ground, from which a:

- 22" Fir bears N17½°W 21.7 ft. to face; scribed T3N R6W S28 BT.
- 9" Fir bears N14¼°E 35.0 ft. to face; scribed T3N R6W S27 BT.
- 24" Fir bears S87½°E 20.0 ft. to face; scribed T3N R6W S34 BT.
- 24" Fir bears S11°W 4.6 ft. to face; scribed T3N R6W S33 BT RS707

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NW of corner pipe. Oregon State Forestry Department metal location poster on SW BT.

Dated January 8, 1976.

Restored by Loren Steele under my direction.  
Loren Steele, Forest Engineer

Present and witnessed by Steve Ellis  
Terry Withrow

BOOK 5

