

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Center-West-East One Sixty-fourth corner for Section 27, T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

OSBF pipe and cap, 1959, (missing in road construction) from which a:

49" Cedar bears N84½°E 56.9 ft.; now 54", scribes, C-W-E 1/64 S27 BT RS401, visible on open face.

33" Hemlock bears N47°W 110.2 ft.; missing, destroyed by road construction.

RESTORED

Var. 21½° East

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY C-W-E 1/64 S27 1976 RS707", 34 inches in ground, in mound of rock, and from which a:

65" Cedar stump bears S33°E 56.6 ft. to face; scribed C-W-E 1/64 S27 BT RS707. Graveled road bears South 95 ft., course S85°E by N83°W.

Set 4" x 4" x 60" white painted Cedar post 3.0 ft. North of corner pipe. Oregon State Forestry Department metal location poster on 65" Cedar stump BT.

Dated June 29, 1976

Restored by Keith D. Whitehead under my direction.  
Keith D. Whitehead, Transitman

Present and witnessed by Mike Nordin

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Harold J. Russell*  
OREGON  
JULY 9, 1965  
HAROLD J. RUSSELL  
707