

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 13 and 24 east side, T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

60" Spruce bears S51° W 21 lks.; now 57" stump, scribes R9W24 visible on open face.

4" Hemlock bears N30°30' W 25 lks.; now 4" up root, scribe marks visible on open face.

RESTORATION by J. S. Forrest, 1950

1½" Iron Pipe (now rusted and broken off at ground level, upper 18" of pipe laying along side from which a:

11" Hemlock bears S75° W 33.3 ft.; now 26", face grown over.

24" Hemlock bears N40° W 78.0 ft.; now 26" uproot, face buried.

RESTORED

Var. 21½° East

Set 1½" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R9W S13 S24 T2S R8W S18 1976 RS707 34 inches in ground, and from which a:

14" Hemlock bears N23 ¾° W 45.9 ft. to face; scribed T2S R9W S13 S24.

26" Hemlock, (Forrest's SW BT) bears S67° W 29.6 ft. to face; scribed RS 707.

CL Graveled Road bears North 251 ft.; course N51° W by S60° E.

Note: Bearings to original BTs were more compatible when measured to B.T. centers than with Forrest's measurements to BT faces.

Forrest's rusted 1½" I.P. bears N82° E 2.9 ft.

Set 4"x4" white painted Cedar post 1.0 ft NE of corner pipe.

Oregon State Forestry Department metal location poster on SW BT.

Also poster on post on South side of gravelled road North 233.0 ft.

Dated November 17, 1976

Restored by Keith D. Whitehead under my direction.  
Keith D. Whitehead, transitman

Present and witnessed by Greer Kelly.

