County Surveyor's Record, Tillamook County, Oregon

CHAINS

BARNES SURVEYING & ENGINEERING, INC.

2565 STATE STREET . SALEM, OREGON . PHONE 581-0911

RESTORED CORNER

Section corner common to Sections 30 and 31, Township 4 North, Range 9 West of the Willamette Meridian and Sections 25 and 36, Township 4 North, Range 10 West of the Willamette Meridian, Clatsop County, Oregon.

OR IG INAL

Post, 4 ft. long 24 ins. in ground marked T4N, S30 on Northeast, R9W, S31 on Southeast, R10W, S36 on Southwest and S25 on Northwest Face.
30 in. Hemlock bears North 60° West 36 lks. marked R10W, T4N, S25 B.T.
24 in. Hemlock bears South 50° West, 29 lks. marked R10W, T4N, S36 B.T.
24 in. Hemlock bears North 10° East, 90 lks. marked T4N, R9W B.T.
Brook, 15 lks. wide, South 7.00 chs.
Summit of low Ridge, East 1.40 chs.
Summit of Bluff, North 2.00 chs.

RESTORED

Set 1" x 30" iron pipe, at toe of bank, which is North 7.00 chs. of Brook, East 1.40 chs. from summit of low Ridge and South 2.00 chs. from summit of Bluff. Found 40" Hemlock rotted stump North 10° East, 90 lks. (No evidence of marks).

16" Alder bears North 75° West 29.5 feet marked with metal location poster.
12" Alder bears South 50° West 31 feet marked with metal location poster.
16" Alder bears South 27° East 23 feet marked with metal location poster.

Dated January 7, 1977

Restored by William G. Curtis, Jr., Pransitman

Present and witnessed by Daniel A. Sporer
Richard W. Montgomery

DAVID L. BASCUE Reg. Land Surveyor Res. 364-0665 ELMER E. SEAY 1 mg Land Planner Res. 363-6103 See my

REGISTERED PROFESSIONAL AND SURVEYOR

OREGON DAVID L. BASCUE

783

Good 6

17