


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was set by the General Land Office in 1933 in a dependant resurvey of T 4 S and R 8 W. They set a brasscap from which,

- 70" Fir Snag N 71° E, 19 Links
- 10" Alder S 83° E, 57 Links
- 24" Fir S 73° E, 163 Links
- 10" Alder S 32° W, 45 Links



Description of corner evidence found:

Found brasscap from which,

18" Fir S 34° W, 29 1/2 feet (L. Whitmore 5-28-1974)  
1933 B.T.'s gone

Description of monument and accessories established to perpetuate the original location of this corner:

Marked 16" D. Fir S 42° E, 128.00 feet

Set 6' Steel fence post and attention sign.

Witness: Marvin Kirk

D. Mike Jackson  
Engineering Technician

*See map B 764*

Office of County Surveyor County of TILLAMOOK  
 State of OREGON, I hereby certify that the within instrument was filed in this office  
 for record on the 8th day of AUGUST, 1977  
[Signature] by County Surveyor  
 (COUNTY OFFICIAL) (DEPUTY)


REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Kenneth M. Wightman*

OREGON  
JULY 17, 1970  
KENNETH M. WIGHTMAN II  
942

Form R6-7100-57 (9/71)

*Book 6 Pg 28*

  
 TIMBERLAND SERVICES, INC.  
 1010 Airport Road P. O. Box 888  
 Albany, Oregon 97321  
 Telephone (503) 926-9404  
 LAND SURVEYING - ENGINEERING  
 LAND USE PLANNING - ROADS  
 FORESTRY CONSULTING

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Edgar R. Cook*

OREGON  
JULY 30, 1976  
EDGAR R. COOK  
1073