

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 19 and 30, T3S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

No evidence of original corner found.

REESTABLISHMENT by State of Oregon--Department of Forestry, 1958.

1 1/2" x 36" galvanized iron pipe with 3" bronze cap (missing, destroyed by cat road construction) from which a:

17" Fir bears N81 1/2°E 51.6 ft.; now 27" stump, face grown over.

10" Fir bears S42 1/2°W 50.7 ft.; now 18", face grown over.

RESTORED

Var 21 1/2° East

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R9W 1/4 S19 S30 1977 RS707", 34 inches in ground, and from which a:

Cat fire trail bears South 10.0 ft. to centerline course N65°E by S68°W.

Set 4" x 4" x 60" white painted Cedar post SE 1.5 ft. from corner pipe. Oregon State Forestry Department metal location poster on 18" Fir BT S42 1/2°W 50.7 ft.. Also poster on 27" Fir stump BT N81 1/2°E 51.6 ft.

Dated September 1, 1977

Restored by Keith D. Whitehead under my direction.
Keith D. Whitehead, Engineer Tech.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Harold J. Russell
OREGON
JULY 9, 1965
HAROLD J. RUSSELL
787

Present and witnessed by Blake Rowe