

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner for Section 7, (West side), T1S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

18" Hemlock bears S59°W 13 lks.; now a 44" uproot.

10" Hemlock bears N62°E 38 lks.; now 10" 5' high rotted stub.

RESTORATION by Louis W. Amort, June 22, 1955.

1½ G.I.P. with 3" brass cap (knocked out of place by uproot and missing) from which a:

24" Spruce bears N54°W 44.7 ft.; now a 34" stump.

23" Spruce bears S89°E 17.0 ft.; now 36", face rotted and partially grown over.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R8W S½S7 RS707 1979", and from which a:

36" Spruce bears S87°E 16.6 ft. to new face; scribed BT along side old face.

36" Fir stub bears N31°E 8.6 ft. to face; scribed ¼S7 BT RS707.

Set 4" x 4" x 60" white painted Cedar post SW .8 ft. from corner pipe.
Oregon State Forestry Department metal location poster on 36" Spruce BT.

Dated April 5, 1979.

Restored by

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Harold J. Russell

OREGON
JULY 9, 1965
HAROLD J. RUSSELL
707

Present and witnessed by Dan Cotton
Joe Hutton