

Tillamook

County

T. 3S., R. 10&11 W., W.M.

Corner Code No.

Segregated Surveys:

Name: Cor to Secs. 6&7, T. 3S., R. 10W., W.M. and Corner No.:

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1 & 12 T. 3S., R. 11W., W.M.

1. History of Corner Establishment and Subsequent Restoration:

Corner was originally established by Albert P. Wilson under government contract No. 552 dated Sept., 1890, who set a 4 in. square post marked "T.3S., R.10W. S6" on NE face, T.3S., R.10W., S7" on SE face, "T.3S., R.11W., S12" on SW face, and "T.3S., R.11W., S1: on NW face, from which: a spruce 30" dia. bears N31°E 81 lks. marked "T.3S., R.10W., S6 BT."; a spruce 30" dia. bears S82°E 60 lks. marked "T.3S., R.10W., S7 BT."; a spruce 36" dia. bears S60°W 47 lks. marked "T.3S., R.11W., S12 BT."; and a spruce 30" dia. bears N50°W 50 lks. marked "T.3S., R.11W., S1 BT." Ernest P. Rands, District Coastal Engineer undertook a dependent resurvey of portions of T.3S., R.10W. in April & May of 1933. He reestablished this corner with a 2"x36" iron post with brass cap, from all found original bearing trees with the NW bearing tree being thence a snag with scribing visible. He set one new bearing tree; a spruce 36" dia. bears N60°W 72 lks. marked T.3S., R.11W., S1 BT."

2. Description of Evidence Found:

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work.

Oregon Coordinate System: Zone, Y, X

Order Accuracy. Derived From:

Pin Pointed on Photo No. 38B-4 Date 6-5-77 Located at CZ Tillamook Hdqtrs.

SURVEYOR'S CERTIFICATE

[SEAL]

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of ORS 209.250, Laws of 1956. Date

Signature

Certificate No.