CERTIFIED RECORD OF LAND CORNER MONUMENTATIO...

History of original corner establishment:

Wilson in 1890 set a post 4" sq., 4' long, 24" in ground, mkd. 4 S on N face from which:

Alder 18" diam. bears $825-2^{\circ}W$, 36 lks. Alder 12" diam. bears N $34^{\circ}E$, 18 lks.

DIAGRAM T6S R10 W

Description of corner evidence found:

Monument found:

4" sq., 36" long post set in a rock mound with visible scribing $\frac{1}{4}S$. This post also found by C.G. Brown, Hebo District Ranger, 1941. Found 5/8" x 48" iron rebar on east edge of post set by L. Whitmore in 1973.

BT's found:

Possible stump hole found S25-120W, 36 lks.

Other orig. BT gone.

Hemlock 10" diam. bears S 630E, 36.3 ft. (Record S 650E, 37 ft.) healed blaze

Hemlock 30" diam. bears N 510W, 18.4 ft. (Record N 530W, 17.7 ft.) healed blaze (Whitmore BT).

Description of monument and accessories I established to perpetuate the original location of this corner: September 14, 1979

Set an aluminum post (with magnet in top and bottom) 30" long, 3" diam., 24" in the ground and in a collar of stone, with aluminim cap mkd.

Orig. post (6" exposed) reset north alongside aluminum post 5/8" iron rebar buried north alongside aluminum post.

T 6 S R 10 W

Accessories:

No additional bearing trees required Painted 6" red band and put ATTN signs on both BT's Placed ATTN sign on post 5'± south

LS 1017 1979

Basis of Bearing

Staff compass was used with a declination of 21°E.

Witness c

Witness Duane Garoutte

Witness

Richard a Chesebro Richard Chesebro

I certify this remonumentation and record thereof, was prepared by me or my assistants under my supervisory direction and is true and correct to the best of my knowledge.

> REGISTERED PROFESSIONAL AND BURVEYOR

Office of County Surveyor County of Tillamook

GORDON H. LONG

State of Oregon , I hereby certify that the within instrument was filed in this office

County Surveyor J. L. Carlich by allam & Dungan (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)